



THIS MAP IS A REPRODUCTION OF THE ORIGINAL MAP
 AND DOES NOT REPRESENT THE CURRENT STATUS OF THE
 LAND OR THE RIGHTS THEREIN. IT IS INTENDED FOR
 INFORMATIONAL PURPOSES ONLY.

Palestine

+3028

BENCH MARKS 1, 2, 5, 6, 7, 8 TOP TOGETHER. ALSO 344
 748 COMPLETELY SEPARATE.

B.M. 1 Top of Bench Post on West Side of Gens. Approx. 100
 Feet West of Northwest Corner of Sec. 18
 on South Side of Road. Elev. 91.69

B.M. 2 Top of Water Eave of Gens. East Side of
 Concrete Drive on Corner Part of the
 30 Rod Line in Fence Along Road on South
 Side of Field on North Side of Road.
 Elev. 94.43

B.M. 3 Top of 7d Galvanized Nails in
 Top of Side of Pole on East Side of
 Line 700 Contained in West Line
 Fence. Elev. 50.00

B.M. 4 Top of Bench Post in South Side of
 Center Corner Post at the North-West
 of Building Lots in Road Fence, East 507

B.M. 5 Spike in West Side of Telephone Pole
 Just East of East Fence of U. P. Line
 30 Rod Line. Elev. 99.38

B.M. 6 Spike on Top of 55' Part South of
 Center of Sec. 12. Elev. 100.06

B.M. 7 Spike on Top of Corner Post 700 Feet
 North of Corner Post 100 Feet
 Elev. 80.00

B.M. 8 West Side of Well Wall on
 East Side of Sec. 12. Elev. 105.70

B.M. 9 Spike in East End of
 Line 1000 on East Side of
 Road. Elev. 94.25

B.M. 10 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 11 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 12 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 13 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 14 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 15 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 16 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 17 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 18 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 19 Spike on
 East Side of
 Road. Elev. 94.25

B.M. 20 Spike on
 East Side of
 Road. Elev. 94.25

